

Assesment performed by:

Kiley Barefoot | Building Inspector

ADDRESS/AREA/STREET RANGE
Corner of Brunswick St and Yacht Basin Dr
Fishy Fishy Restauarant
Yacht Basin Dr
End of W. West St
End of Yacht Basin / American Fish / Condos
E Bay St / Provisions parking lot
Olivers / E Bay St and N Howe
Waterfront area
E Bay and S Atlantic
N. Atlantic and E West St
River Dr and E Moore
125 Cape Fear
224 River Dr
Prices Creek
Trout Lily and Prices Creek
Smithville Woods
Indigo
Northwood Cemetery
Smithville Cemetery
The Landing
Navigator Way
Riversound Cir
Hammocks
Rivermist
Turtlewood
Lowe White Park

10/1/22

Public Services Director | Tom Stanley

DESCRIPTION	RATE DAMAGE 1 THRU 6
Lg dumpster from Fishy Fishy (traveled with flooding)	1
Outdoor mechanical doors loose and hanging / walk in coolers flooded	1
Minor Flooding	1
Street light hanging from pole	1
Minor Flooding	1
Parking shack blown over	1
Flooding	1
Flooding, sand on top of end of sidewalk concrete pad uncovered, bench damaged, City pier and dock okay to open	1
Bulkhead damaged	2
Tree down behind City Gym / Parks and Rec	1
Minor debris on road	1
Tree down on personal property	1
Tree on line (power has been restored)	1
Minor debris on road	1
Street sign hanging	1
Minor debris on road	1
Minor debris on road	1
Tree/bush blown over at beginning of Chinquapin / Lg tree limb hanging between dogwood and fig	1
Minor debris on road	
Minor debris on road	1
Tree down on personal property	1
Street speed sign fallen over	1
Small tree uprooted	1
Clear	0
Minor debris on road	1
Clear	0